

Error Codes When Receiving a Fax with a IJP-V100 Printer

Below is a table of the Error Codes for the fax receiving on the IJP-V100 printer:

Error Code	Error Definition
223 ECM, 224	One or more received pages may not be readable
225 226 227 228 229 230 231	There is a feature incompatibility with the sending fax machine.
232 233 234 235 ECM 236 ECM 237	The telephone connection was lost.
238 239 ECM 240 ECM 241 ECM	The sending fax machine sent an unexpected communication.
242	The remote fax machine is attempting to receive instead of send.
243 244 245 ECM 246 ECM	The sending fax machine prematurely ended the session.

252	Telephone line conditions were too poor to receive a fax.
253	The sending fax machine attempted to use an unsupported page width.
281 282 ECM 283 284 285 ECM 286	The telephone connection was lost.
290	There was a communication error with the sending fax machine.
291	The received fax could not be stored.