

How to Reinstall the Sound Drivers? PCV E302DS E308DS

Follow these steps to reinstall the Sound Drivers on a PCV E302DS E308DS.

1. Insert the Application Recovery CD into the CDROM drive.
2. At the Welcome screen, click OK.
3. Double-click the Drivers folder.
4. Double-click the Audio Driver icon.
5. Read the text box and then click X to close it.
6. At the ASP4SETP box, click Yes.
7. Click OK to exit the Sony Application Recovery CD.

NOTE: Leave the Application Recovery CD in the drive as the computer restarts.

8. At the Add New Hardware Wizard box, click Next.
9. Select 'Search for the best driver...' and click Next.
10. Select Specify a Location.
11. In the box, type G:\drivers\audio\AL98091701\English and click Next.
12. Click Next.
13. Click Finish.